








cvi42[®]

Mac OS Quick Keys

BASICS













Undo	 + 	Refresh Study List	
Redo	 + 	Add to Case Review	 + 
Delete Selected		Contours ON/OFF	 +  + 
Copy Selected	 + 	Zoom to Phase Navigation	 + 
Copy All	 + 	Fullscreen	 + 
Paste	 + 	Preferences	 + 
Hide All		View All Images in Multi-View	
Play Cine		Go to Next/Previous Series	 / 

WINDOW


Default	 + 
Auto (Type 1)	
Auto (Type 2)	
Auto (Type 3)	
Auto (Min Max)	
Hide cvi42	 + 
Hide Others	 +  + 

Contours







DELETE

Delete All	 + 
Delete All (Slice)	 + 
Delete All (Phase)	 + 
Cut Selected	 + 
Delete Selected (Slice)	 + 
Delete Selected (Phase)	 + 










FORWARD

Forward All	 + 
Forward Selected	 + 
Select and Jump to Next	

MOVE

Drag	 + 
Push	 + 
Reposition All	 + 

EDIT

Smooth	 + 
Round	 + 
Refine	
Click-Draw	 + 
Threshold Contour Definition	 + 

Mac and the Mac logo are trademarks of Apple Inc., registered in the U.S. and other countries.
Quick Keys Valid for cvi42 v5.12 & cvi42 v5.13