

BASICS

Undo		Refresh Study List	
Redo		Add to Case Review	
Delete Selected		Contours On/ Off	+ +
Copy Selected		Zoom to Phase Navigation	+
Copy All		Fullscreen	
Paste		Preferences	
Hide All		View All Images in Multi-view	
Play Cine			

WINDOW

Default	
Auto (Type 1)	
Auto (Type 2)	
Auto (Type 3)	
Auto (Min Max)	
Hide cvi42	
Hide Others	+ +

CONTOURS

DELETE

Delete All	
Delete All (Slice)	
Delete All (Phase)	
Cut Selected	
Delete Selected (Slice)	
Delete Selected (Phase)	

FORWARD

Forward All	
Forward Selected	
Select and Jump to Next	

MOVE

Drag	+
Push	+
Reposition All	+

EDIT

Smooth	
Round	
Refine	hold
Click-Draw	+
Threshold Contour Definition	+

BASICS

Undo		Refresh Study List	
Redo		Add to Case Review	
Delete Selected		Contours On/ Off	
Copy Selected		Zoom to Phase Navigation	
Copy All		Fullscreen	
Paste		Preferences	
Hide All		View All Images in Multi-view	
Play Cine			

WINDOW

Default	
Auto (Type 1)	
Auto (Type 2)	
Auto (Type 3)	
Auto (Min Max)	

CONTOURS

DELETE

Delete All	
Delete All (Slice)	
Delete All (Phase)	
Cut Selected	
Delete Selected (Slice)	
Delete Selected (Phase)	

FORWARD

Forward All	
Forward Selected	
Select and Jump to Next	

MOVE

Drag	
Push	
Reposition All	

EDIT

Smooth	
Round	
Refine	
Click-Draw	
Threshold Contour Definition	